

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans **Run date** 22-Nov-14 **Time** 8:07 AM

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 667 Const Calendar Day: 885 Date: 06-Nov-2014 Thursday Inspector Name: Feather, Bernard Title: Transportation Engineer

Inspection Type: Intermittent

Shift Hours: 08:00 am 05:00 pm Break: 01:00 Over Time:

Federal ID: Location:

Reviewer: Shedd, Bill Approved Date: Status: Submit

Weather

Temperature 7 AM 12 PM 4PM

Precipitation Condition clear, warm, moderate breeze

Working Day 🗸 If no, explain:

Diary:

General Comments

Weekly safety meeting 0800-0845. Elevator landing gate and diaphram panel inspection. Process response to Submittal 3067R03. Elevator keys were deliverd to the Department. Misc MEP paperwork and write diaries.

04-0120F4 Bid Item: 098 0-000-000.098 ELEVATOR

AMERICAN BRIDGE/FLUOR, A JV

Diary:

Elevator 098 0-000-000.098

Bill O'Sullivan sent an email to Robby Bailey, US Hoist, showing the mounting location for the intercominside the elevator control room.

ABF delivered 4 sets of elevator keys to the Department.

At 0930, I met Bill O'Sullivan at the Pier 7 boat dock and we took a crew boat to T1 to perform an inspection of the tower landing gates and diaphram panels. During a previous inspection, it was noted that all these gates and landings had a film of MEP salts for the cleaning of the elevator shaft and tower shafts, and several of the gates needed touchup paint work.

Bill O'Sullivan and I climbed from Elevation 15M to Elevation 156M inspecting the gates at every diaphram and landing. All panels and gates were cleaned to my satisfaction with the exception of the following:

At Elevation 38M, the paint is chipped on the panel and the panel needs further cleaning. The elevator was parked at the Diaphram at Elevation 27M, and I could look over the top of the panel to the top of the elevator. I noted that trash, and paint chips were present on the roof of the elevator cab.

At Elevation 43M, the "Danger High Voltage Sign" is damaged in that solvent has washed out the lettering.

At Elevaton 77M, the "Danger High Voltage Sign" is damaged in that solvent has washed out the lettering.

At 1230, Bill O'Sullivan and I returned to Pier 7 via crew boat.

Daily Diary Report by Bid Item

Inspector Name Feather, Bernard Job Name: 04-0120F4 Diary #: 667 Date: 06-Nov-2014 DEHUMIDIFIER SYSTEM 04-0120F4 Bid Item: 0-000-000.128 AMERICAN BRIDGE/FLUOR, A JV Dispute Diary: **Tower Base Dehumidification** 128 0-000-000.128

Bill O'Sullivan and I went to the tower base dehumidification unit and changed the set point to 20% RH.



System